

Certificate of Conformity

Certificate Number: B-E16059776

EMC Directive 2014/30/EU

Beide
Compliance Laboratory

Holder.....: Tianjin Geneuo Technology Co., Ltd.
Address.....: Technology Avenue South, Jinghai Development Area,
Tianjin City, China
Manufacturer.....: Same As Holder
Product.....: Over Moulding Connector (M8,M12,M16,M23,7/8")
Model No.....: See Appendix A
Technical Data....: DC 24V


The submitted products have been tested by us with the following standard(s) and found to be in compliance with the listed European Directives.

EN 61000-6-3:2007+A1:2011;
EN 61000-6-1:2007

The test results apply only to the particular sample tested and to the specific tests carried out. Technical Report and documentation are at the Holder's disposal.

This certificate applies specifically to the sample investigated in our test reference number only. The CE markings as shown below can be affixed on the product after preparation of necessary technical documentation. Other relevant Directives have to be observed.




Certification Manager
Date: May 12, 2016



Company No.07113834



Beide (UK) Product Service Limited

U.K.: Flat 107, 25 Indecon Square, London, United Kingdom

China: 6F, Bldg E, Hourui 3rd Ind Zone, Xixiang, Bao'an Dist, Shenzhen, China

Http://www.szbeide.com E-mail:admin@szbeide.com

Appendix A

EK [^] *M/...	SK [^] *M/...	EQK [^] *M/...	RK [^] *M/...	SK [^] EZ [^] *M/...
EZ [^] *M/...	SZ [^] *M/...	EQZ [^] *M/...	RZ [^] *M/...	EK [^] SZ [^] *M/...
ELK [^] *M/...	SLK [^] *M/...	EQLK [^] *M/...	RLK [^] *M/...	SLK [^] ELZ [^] *M/...
ELZ [^] *M/...	SLZ [^] *M/...	EQLZ [^] *M/...	RLZ [^] *M/...	SLK [^] EZ [^] *M/...
EK [^] EZ [^] *M/...	SK [^] SZ [^] *M/...	EQK [^] EQZ [^] *M/...	RK [^] RZ [^] *M/...	SK [^] ELZ [^] *M/...
ELK [^] ELZ [^] *M/...	SLK [^] SLZ [^] *M/...	EQLK [^] EQLZ [^] *M/...	RLK [^] RLZ [^] *M/...	EK [^] SLZ [^] *M/...
EK4112-0/7	SK3212-0	VA21-024-*M-LV	YWZ [^] -2EK [^]	ELK [^] SZ [^] *M/...
EZ4112-0/7	SZ3212-0	VA21-110-*M-LV	YWK [^] -2EZ [^]	ELK [^] SLZ [^] *M/...
EK4112-0/9	SK4212-0	VA21-220-*M-LV	YVZ [^] -2EK [^]	ELK [^] P2-*M/...
EZ4112-0/9	SZ4212-0	VB21-024-*M-LV	YVK [^] -2EZ [^]	EK [^] P2-*M/...
ELK4112-0/7	DNK6-4-*M/...	VB21-110-*M-LV	YSK4-2SZ3-*M-*M/...	SLK [^] P2-*M/...
ELZ4112-0/7	DNLK6-4-*M/...	VB21-220-*M-LV	YSZ4-2SK3-*M-*M/...	SK [^] P2-*M/...
EK5112-0/7	DWZ6-4-*M/...	VBR21-024-*M-LV	YK4-2EZ3-*M-*M/...	ELK [^] P3-*M/...
EZ5112-0/7	DWLZ6-4-*M/...	VBR21-110-*M-LV	YK4-2SZ3-*M-*M/...	ELK [^] P3.1-*M/...
EK5112-0/9	DNK6-6-*M/...	VBR21-220-*M-LV	YZ4-2EK3-*M-*M/...	RLK [^] P2-*M/...
EZ5112-0/9	DNLK6-6-*M/...	VBI21R-024-*M-LV	YZ4-2SK3-*M-*M/...	RK [^] P2-*M/...
ELK5112-0/7	DWZ6-6-*M/...	VBI21R-110-*M-LV	EILZ8-*M/E41	EPK5-*M
ELZ5112-0/7	DWLZ6-6-*M/...	VBI21R-220-*M-LV	FEIK81-*M/E41	EPLK5-*M
MK [^] *M	DNK14-10-*M/...	GNZ19-11-*M/...	FEIZ81-*M/E41	EPZ5-*M
MZ [^] *M	DNLK14-10-*M/...	GNLZ19-11-*M/...	RJ45S-*M/E41	EPLZ5-*M
MLK [^] *M	DWZ14-10-*M/...	GNK19-17-*M/...	TRJ45S-*M/E41	EPK5 EPZ5-*M
MLZ [^] *M	DWLZ14-10-*M/...	GNLK19-17-*M/...	BRJ45S-*M/E41	EPK5 EPLZ5-*M
MK [^] *M	MK [^] MLZ [^] *M	GNZ19-17-*M/...	EIK4-*M/F41	EPLK5 EPZ5-*M
MZ [^] *M	MLK [^] MLZ [^] *M	GNLZ19-17-*M/...	EIZ4-*M/F41	EPLK5 EPLZ5-*M
MLK [^] *M	MK [^] MZ [^] *M/24	GNK19-19-*M/...	EILK4-*M/F41	MLK [^] MZ [^] *M

Note: [^]on behalf of the number of cable core, * on behalf of the cable length,...On behalf of the cable material



Company No.07113834



Beide (UK) Product Service Limited

U.K.: Flat 107, 25 Indecon Square, London, United Kingdom

China: 6F, Bldg E, Hourui 3rd Ind Zone, Xixiang, Bao'an Dist, Shenzhen, China

Http://www.szbeide.com E-mail: admin@szbeide.com

MK^*M/20	GNK12-11-*M/...	GNLK19-19-*M/...	EILZ4-*M/F41	GNLK19-11-*M/...
MZ^*M/20	GNLK12-11-*M/...	GNZ19-19-*M/...	FEIK41-*M/F41	EILK8-*M/E41
MLK^*M/20	GNZ12-11-*M/...	GNLZ19-19-*M/...	FEIZ41-*M/F41	BRJ45S-*M/F41
MLZ^*M/20	GNLZ12-11-*M/...	EIK8-*M/E41	RJ45S-*M/F41	MK^ MZ^*M
GNK19-11-*M/...	EIZ8-*M/E41	TRJ45S-*M/F41	FMNK52-*M/...	FMNZ52-*M/...
ENZ5-*YK5- ENK5-0024-LDC	FEK^&	FDWZ^*M/20	FW-VA21-^*M/...	MNZ5-ENK5-MNK5
ENLZ5-*YLK5- ENLK5-0024-LDC	FEZ^&	FDNK^2-L/M20	FW-VA22-^*M/...	ENZ5-2ENK5-V
ETK4-*M/...	FEK^ FEZ^/M12	FDWZ^2-L/M20	FW-VA31-^*M/...	ENK5-TR
ETZ4-*M/...	FEBK5 FEBZ5/M12	GNK^*M/...	ENK5-*M/10	ENZ5-TR
EK4242-0/11	SKD^*M/...	GNZ^*M/...	ENLK5-*M/10	MNK5-TR
EZ4242-0/11	SZD^*M/...	GNLK^*M/...	ENZ5-*M/10	MNZ5-TR
FETK4^*	FSK^&/M8	GNLZ^*M/...	ENLZ5-*M/10	MNZ5-TR/VM
FETZ4^*	FSZ^&/M8	GNK^28-0/M22/C	ENK5 ENZ5-*M/10	MNK5-TR/VM
EK^111-0/11	MZ^2MK^/...	GNK^28-0/M22/L	ENLK5 ENLZ5-*M/10	YZW^*M-2EK ^*M-*M/...
EZ^111-0/11	MK^211-0/11	GNZ^28-0/M22/L	MNK5-*M	EK4238-0/9
ELK^111-0/11	MZ^211-0/11	GNLK^28-0/M22/L	MNLK5-*M	EZ4238-0/9
ELZ^111-0/11	MLK^211-0/11	GNLZ^28-0/M22/L	MNZ5-*M	ELK4238-0/9
EK^114-0/11	MLZ^211-0/11	FGWK^*M/...	MNLZ5-*M	ELZ4238-0/9
ELK^114-0/11	MK^212-0/11	FGWZ^*M/...	MNK5 MNZ5-*M/10	RJ45/...
EK^218-0/9	MZ^212-0/11	FGWK^2-L/M20	MNLK5 MNLZ5-*M/10	EPK5-2EPZ5-V
EZ^218-0/9	MLK^212-0/11	FGWZ^2-L/M20	JBS6MNK-DN	EPZ5-TR
ELK^218-0/9	MLZ^212-0/11	VA31-^*M-...	JBS4MK-4	EK5228-0/9
ELZ^218-0/9	FMK^2-*M/20	VA32-^*M-L	JBS6MK-4	EZ5228-0/9
EK^11^1/11	FMZ^2-*M/20	VC21-^*M-...	JBS8MK-4	ELK5228-0/9
EZ^11^1/11	FDNK^*M/20	VCI21-^*M-...	MNZ5--2MNK5	ELZ5228-0/9
JB6MNK-DN	JBS4MNK-DN			

Note: ^on behalf of the number of cable core, * on behalf of the cable length,...On behalf of the cable material



Company No.07113834



Beide (UK) Product Service Limited

U.K.: Flat 107, 25 Indecon Square, London, United Kingdom

China: 6F, Bldg E, Hourui 3rd Ind Zone, Xixiang, Bao'an Dist, Shenzhen, China

Http://www.szbeide.com E-mail: admin@szbeide.com